

HantekXXXX USB software and driver installation


HantekXXXX USB software and driver installation under Win7, Win8 and Win10.

Software Installation


1. Insert the Hantekxxxx USB installation CD into the CD-ROM drive.
2. The installation should start up automatically. Otherwise in Windows Explorer, switch to the CD-ROM drive and run 'Setup.exe'.




3. The Hantekxxxx USB installation is started. Click 'Next' to continue.




4. Choose a destination directory. Click 'Next' to continue.




5. Check the setup information. Click Next to start copying of files.



6. This status dialog is displayed during copying of files.



7. Updating System Configuration.




8. The installation is completed.




Driver Installation


1. Connect the Hantekxxxx USB to your PC.
2. New hardware is found. Click "**Locate and install driver software (recommended)**".




3. Click "Browse my computer for driver software".




4. Specific the path of driver or CD. Then click "Next".







5. Click "Install this driver software anyway".



6. Installing driver software.




7. Hantekxxxx USB driver1 has been successfully installed. Click "Close".



8. Please wait for a while, Hantekxxxx USB dirver2 will be installed automatically.

9. The device driver is installed successfully and your device is ready to use.



10. Run "Hantekxxxx USB" software. The software installation is OK.